


















		упак	роздріб	\$			упак	роздріб	\$
<b>Труба PN20</b>					<b>Перехідник редукційний ЗВ</b>				
	111.1R.D12.EC4	20x3,4	100	<b>0.75</b>		112.1R.A06.FE0	25/20	50/200	<b>0.09</b>
	111.1R.D12.FC4	25x4,2	100	<b>1.30</b>		112.1R.A06.GE0	32/20	60/120	<b>0.14</b>
	111.1R.D12.GC4	32x5,4	100	<b>2.40</b>		112.1R.A06.GF0	32/25	60/120	<b>0.18</b>
	111.1R.D12.HC4	40x6,7	60	<b>3.62</b>		112.1R.A06.HE0	40/20	25/75	<b>0.25</b>
	111.1R.D12.IC4	50x8,3	40	<b>5.62</b>		112.1R.A06.HF0	40/25	25/75	<b>0.27</b>
	111.1R.D12.JC4	63x10,5	28	<b>8.92</b>		112.1R.A06.HG0	40/32	15/105	<b>0.34</b>
	111.1R.D12.KC4	75x12,5	20	<b>12.73</b>		112.1R.A06.IE0	50/20	20/40	<b>0.40</b>
	111.1R.D12.LC4	90x15,0	12	<b>18.96</b>		112.1R.A06.IF0	50/25	20/40	<b>0.42</b>
	111.1R.D12.MC4	110x18,3	8	<b>27.79</b>		112.1R.A06.IG0	50/32	15/45	<b>0.44</b>
	211.1R.D12.NC4*	125x20,8	4			112.1R.A06.IH0	50/40	15/45	<b>0.50</b>
<b>Труба Stabi</b>					<b>Трійник</b>				
	111.1R.A21.E04	20x3,4	100	<b>1.50</b>		112.1R.A04.E00	20	25/100	<b>0.16</b>
	111.1R.A21.F04	25x4,2	100	<b>2.12</b>		112.1R.A04.F00	25	15/60	<b>0.25</b>
	111.1R.A21.G04	32x5,4	60	<b>3.47</b>		112.1R.A04.G00	32	8/48	<b>0.45</b>
	111.1R.A21.H04	40x6,7	60	<b>4.99</b>		112.1R.A04.H00	40	6/30	<b>0.73</b>
	111.1R.A21.I04	50x8,3	40	<b>7.42</b>		112.1R.A04.I00	50	3/12	<b>1.25</b>
	111.1R.A21.J04	63x10,5	28	<b>11.55</b>		112.1R.A04.J00	63	2/6	<b>2.65</b>
	111.1R.A21.K04	75x12,5	20	<b>16.21</b>		112.1R.A04.K00	75	4	<b>5.34</b>
	111.1R.A21.L04	90x15,0	12	<b>22.86</b>		112.1R.A04.L00	90	2	<b>7.94</b>
	111.1R.A21.M04	110x18,3	8	<b>32.99</b>		112.1R.A04.M00	110	1	<b>13.62</b>
<b>Труба Faser (скловолокно)</b>					<b>Трійник редукційний</b>				
	111.1R.D62.EC4	20x3,4	100	<b>1.25</b>		112.1R.A05.EFE	20x25x20	25/75	<b>0.25</b>
	111.1R.D62.FC4	25x4,2	100	<b>1.78</b>		112.1R.A05.FEE	25x20x20	25/75	<b>0.26</b>
	111.1R.D62.GC4	32x5,4	60	<b>2.95</b>		112.1R.A05.FEE	25x20x25	25/75	<b>0.27</b>
	111.1R.D62.HC4	40x6,7	40	<b>4.03</b>		112.1R.A05.FFE	25x25x20	25/75	<b>0.31</b>
	111.1R.D62.IC4	50x8,3	20	<b>6.31</b>		112.1R.A05.GEE	32x20x20	15/45	<b>0.40</b>
	111.1R.D62.JC4	63x10,5	20	<b>10.48</b>		112.1R.A05.GEF	32x20x25	15/45	<b>0.42</b>
	111.1R.D62.KC4	75x12,5	12	<b>15.11</b>		112.1R.A05.GEG	32x20x32	10/40	<b>0.43</b>
	111.1R.D62.LC4	90x15,0	12	<b>21.92</b>		112.1R.A05.GFE	32x25x20	10/40	<b>0.40</b>
	111.1R.D62.MC4	110x18,3	8	<b>31.67</b>		112.1R.A05.GFG	32x25x32	8/48	<b>0.49</b>
<b>Коліно 90°</b>					<b>Коліно ніпельне 90°</b>				
	112.1R.A02.E00	20	50/150	<b>0.13</b>		7711002020	20	100	<b>0.15</b>
	112.1R.A02.F00	25	25/100	<b>0.18</b>		7711002025	25	50	<b>0.33</b>
	112.1R.A02.G00	32	25/50	<b>0.33</b>	<b>Коліно 45°</b>				
	112.1R.A02.H00	40	5/35	<b>0.56</b>		112.1R.A03.E00	20	50/150	<b>0.17</b>
	112.1R.A02.I00	50	4/20	<b>1.10</b>		112.1R.A03.F00	25	20/80	<b>0.23</b>
	112.1R.A02.J00	63	2/8	<b>2.14</b>		112.1R.A03.G00	32	15/60	<b>0.35</b>
	112.1R.A02.K00	75	5	<b>3.86</b>		112.1R.A03.H00	40	7/35	<b>0.59</b>
	112.1R.A02.L00	90	2	<b>6.44</b>		112.1R.A03.I00	50	5/20	<b>1.40</b>
	112.1R.A02.M00	110	2	<b>11.46</b>		112.1R.A03.J00	63	2/8	<b>2.27</b>
<b>Муфта</b>					<b>Кріплення</b>				
	112.1R.A01.E00	20	50/200	<b>0.10</b>		112.1R.A16.E00	20	100/30C	<b>0.06</b>
	112.1R.A01.F00	25	60/120	<b>0.15</b>		112.1R.A16.F00	25	100/20C	<b>0.10</b>
	112.1R.A01.G00	32	15/105	<b>0.24</b>		112.1R.A16.G00	32	50/150	<b>0.12</b>
	112.1R.A01.H00	40	15/60	<b>0.36</b>		212.1R.A13.H00	40	50/100	<b>0.20</b>
	112.1R.A01.I00	50	5/30	<b>0.60</b>		212.1R.A13.H00	50	50/100	<b>0.59</b>
	112.1R.A01.J00	63	12	<b>1.22</b>		212.1R.A13.H00	63	50/100	<b>1.31</b>
	112.1R.A01.K00	75	12	<b>1.85</b>		212.1R.A13.H00	75	50/100	<b>1.70</b>
	112.1R.A01.L00	90	5	<b>3.02</b>		212.1R.A13.H00	110	50/100	<b>3.00</b>
	112.1R.A01.M00	110	4	<b>5.30</b>	<b>Кріплення подвійне</b>				
<b>Заглушка</b>						7733000021	20	100/70C	<b>0.11</b>
	112.1R.A07.E00	20	50/300	<b>0.10</b>		7733000026	25	100/40C	<b>0.14</b>
	112.1R.A07.F00	25	100/200	<b>0.14</b>	<b>Коліно монтажне</b>				
	112.1R.A07.G00	32	50/100	<b>0.21</b>		112.1R.B14.EQ0	20x1/2"	15/60	<b>1.07</b>
	112.1R.A07.H00	40	15/60	<b>0.36</b>		112.1R.B14.FQ0	25x1/2"	15/60	<b>1.28</b>
	112.1R.A07.I00	50	10/40	<b>0.65</b>	<b>Кріплення</b>				
	112.1R.A07.J00	63	6/24	<b>1.54</b>		112.1R.A16.E00	20	100/30C	<b>0.06</b>
	112.1R.A07.K00	75	2/10	<b>2.59</b>		112.1R.A16.F00	25	100/20C	<b>0.10</b>
	112.1R.A07.L00	90	4	<b>3.68</b>		112.1R.A16.G00	32	50/150	<b>0.12</b>
	112.1R.A07.M00	110	4	<b>6.34</b>		212.1R.A13.H00	40	50/100	<b>0.20</b>
<b>Заглушка різьбова</b>						212.1R.A13.H00	50	50/100	<b>0.59</b>
	112.1R.A08.E00	20	100/300	<b>0.09</b>		212.1R.A13.H00	63	50/100	<b>1.31</b>
	112.1R.A08.F00	25	100/300	<b>0.12</b>		212.1R.A13.H00	75	50/100	<b>1.70</b>
	112.1R.A08.G00	32	50/150	<b>0.14</b>		212.1R.A13.H00	110	50/100	<b>3.00</b>

**Обвідне коліно**

113.1R.M12.E00	20	50	<b>0.43</b>
113.1R.M12.F00	25	40	<b>0.66</b>
113.1R.M12.G00	32	25	<b>1.34</b>

**Муфта ВР**

112.1R.B11.EQ0	20x1/2"	30/120	<b>0.82</b>
112.1R.B11.ER0	20x3/4"	20/80	<b>1.24</b>
112.1R.B11.FQ0	25x1/2"	15/60	<b>1.04</b>
112.1R.B11.FR0	25x3/4"	15/60	<b>1.15</b>
112.1R.B11.GS0	32x1"	8/40	<b>3.59</b>
112.1R.B11.HT0	40x1 1/4"	4/20	<b>7.07</b>
112.1R.B11.IU0	50x1 1/2"	4/16	<b>9.30</b>
112.1R.B11.JV0	63x2"	2/10	<b>12.90</b>
112.1R.B11.KW0	75 x 2 1/2"	5	<b>18.42</b>

**Муфта ЗР**

112.1R.B21.EQ0	20x1/2"	20/80	<b>1.06</b>
112.1R.B21.ER0	20x3/4"	15/60	<b>1.60</b>
112.1R.B21.FQ0	25x1/2"	15/60	<b>1.43</b>
112.1R.B21.FR0	25x3/4"	15/60	<b>1.82</b>
112.1R.B21.GS0	32x1"	6/24	<b>4.71</b>
112.1R.B21.HT0	40x1 1/4"	4/12	<b>10.40</b>
112.1R.B21.IU0	50x1 1/2"	4/12	<b>11.00</b>
112.1R.B21.JV0	63x2"	2/10	<b>15.94</b>
112.1R.B21.KW0	75x2 1/2"	8	<b>23.00</b>

**Фланець**

112.1R.A10.J00	63	18	<b>1.82</b>
112.1R.A10.K00	75	12	<b>2.99</b>
112.1R.A10.L00	90	6	<b>4.02</b>
112.1R.A10.M00	110	6	<b>6.04</b>

**Трійник ВР**

112.1R.B13.EQ0	20x1/2"x20	15/60	<b>1.10</b>
112.1R.B13.ER0	20x3/4"x20	15/60	<b>1.52</b>
112.1R.B13.FQ0	25x1/2"x25	10/40	<b>1.16</b>
112.1R.B13.FR0	25x3/4"x25	10/40	<b>1.56</b>
112.1R.B13.FR0	32x3/4"x32	20	<b>1.86</b>
7751032254	32x1"x32	20	<b>3.94</b>

**Трійник ЗР**

112.1R.B23.EQ0	20x1/2"x20	15/60	<b>1.92</b>
7754020127	20x3/4"x20	20	<b>2.36</b>
112.1R.B23.FQ0	25x1/2"x25	10/40	<b>2.29</b>
112.1R.B23.FR0	25x3/4"x25	8/40	<b>3.45</b>

**Муфта-гайка ВР**

112.1R.G12.EQ0	20 x1/2"	20/80	<b>3.24</b>
112.1R.G12.FR0	25 x3/4"	15/60	<b>3.45</b>
112.1R.G12.GS0	32 x 1"	10/40	<b>6.77</b>
112.1R.G12.HT0	40x1 1/4"	5/20	<b>10.44</b>

**Муфта-гайка ЗР**

112.1R.G22.EQ0	20x1/2"	15/60	<b>3.37</b>
112.1R.G22.FR0	25x3/4"	10/40	<b>5.18</b>
112.1R.G22.GS0	32x1"	6/24	<b>5.18</b>
112.1R.G22.HT0	40x1 1/4"	4/16	<b>10.57</b>

**Комплект: паяльник, насадки, ножиці, рулет**

8791020040	20-63мм	5	<b>111.02</b>
214.10.1C0.C00	50-110мм	1	<b>287.77</b>

**Зачишувач для труб Stabi**

214.10.3B0.EF0	20-25мм	10	<b>25.84</b>
8795032040	32-40мм	5	<b>19.58</b>
8795050063	50-63мм	5	<b>28.17</b>
8795063075	75мм		<b>53.84</b>

**Зачишувач для Stabi під перфоратор**

87950630720	20мм		<b>9.93</b>
87950630725	25мм		<b>10.36</b>
87950630732	32мм		<b>10.82</b>

**Насадки для зварки**

214.10.1A0.E00	20мм		<b>5.45</b>
214.10.1A0.F00	25мм		<b>5.53</b>
214.10.1A0.G00	32мм		<b>6.45</b>
8793000040	40мм		<b>8.44</b>
214.10.1A0.I00	50мм		<b>12.16</b>
214.10.1A0.J00	63мм		<b>15.94</b>
214.10.1A0.K00	75мм		<b>23.16</b>
214.10.1A0.L00	90мм		<b>33.11</b>
214.10.1A0.M00	110мм		<b>47.34</b>

**Хрестовина**

112.1R.A13.E00	20	15/60	<b>0.25</b>
112.1R.A13.F00	25	10/40	<b>0.31</b>
112.1R.A13.G00	32	8/32	<b>0.60</b>
112.1R.A13.H00	40	5/20	<b>0.88</b>

**Шаблон для змішувача з колінами 20x1/2В**

комплект	20x1/2"	50	<b>2.30</b>
----------	---------	----	-------------

**Коліно ВР**

112.1R.B12.EQ0	20x1/2"	20/80	<b>1.06</b>
112.1R.B12.FQ0	25x1/2"	15/60	<b>1.14</b>
112.1R.B12.FR0	25x3/4"	15/60	<b>1.56</b>
7772032191	32x3/4"	10	<b>2.15</b>
112.1R.B12.GS0	32x1"	20	<b>3.74</b>

**Коліно ЗР**

112.1R.B22.EQ0	20x1/2"	15/60	<b>1.20</b>
7774020191	20x3/4"	20	<b>1.67</b>
112.1R.B22.FQ0	25x1/2"	10/40	<b>1.68</b>
112.1R.B22.FR0	25x3/4"	10/40	<b>2.14</b>
112.1R.B22.GS0	32x1"	16	<b>5.56</b>

**Кран вентиль**

112.1R.C10.EQ0	20	6/24	<b>5.00</b>
112.1R.C10.FR0	25	5/20	<b>5.23</b>
112.1R.C10.GS0	32	4/16	<b>7.99</b>

**Кран вентиль хром.**


112.1R.C30.EQ0	20	20	<b>10.83</b>
112.1R.C30.FR0	25	20	<b>12.18</b>
112.1R.C30.GS0	32	16	<b>11.65</b>

**Кран шаровий**

112.1R.C20.EQ0	20	5/20	<b>4.76</b>
112.1R.C20.FR0	25	4/16	<b>6.37</b>
112.1R.C20.GS0	32	2/8	<b>10.97</b>

**Кран шаровий з американками**

212.1R.A16.E00	20	12	<b>12.87</b>
212.1R.A16.F00	25	12	<b>16.49</b>
212.1R.A16.G00	32	12	<b>22.11</b>
212.1R.A16.H00	40	12	<b>25.77</b>
212.1R.A16.I00	50	12	<b>30.48</b>
212.1R.A16.J00	63	12	<b>39.10</b>
212.1R.A16.K00	75	4	<b>101.19</b>
212.1R.A16.L00	90	4	<b>100.98</b>

**Американка пластикова**

212.1R.A15.E00	20	25/50	<b>2.33</b>
212.1R.A15.F00	25	20/40	<b>3.23</b>
212.1R.A15.G00	32	10/20	<b>4.65</b>
212.1R.A15.H00	40	5/15	<b>5.08</b>
212.1R.A15.I00	50	5/10	<b>6.93</b>
212.1R.A15.J00	63	5	<b>8.64</b>
212.1R.A15.K00	75	2	<b>20.23</b>
212.1R.A15.L00	90	1	

**Колектор**

112.1R.A09.GE0	32 - 20	10/30	<b>0.69</b>
112.1R.A09.HE0	40 - 20		<b>1.82</b>

**Ножиці для PPR**

214.10.2A0.E00	16-40		<b>18.14</b>
80937	16-32		<b>11.06</b>

**Труба PEX-b з кисневим бар'єром**

141.1K.A35.C00	16x2	160	<b>0.86</b>
----------------	------	-----	-------------

**Труба PEX-b без кисневого бар'єру**

141.1B.A15.C0P	16x2	160	<b>0.66</b>
----------------	------	-----	-------------

